

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 6,893,101

USPTO CONFIRMATION CODE: 1029

APPLICATION NO.: 09/917,573

FILED: July 27, 2001

EXAMINER: Michael B Shingleton

GROUP ART UNIT: 2817

FOR: ACTIVE ELEMENT BIAS CIRCUIT FOR RF POWER TRANSISTOR INPUT

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION  
FOR USPTO MISTAKE

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

SIR:

The following is a request for a certificate of correction in Serial Number 09/917,573, now Patent Number 6,893,101.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 50-1379. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

On the Face Page, in Field (56), under "FOREIGN PATENT DOCUMENTS", in Column 2, Line 3, delete "JP 1079515 2/2001" and insert - - EP 1079515 2/2001 - -, therefor.

(LIST OF REFERENCES CITED BY APPLICANT AND CONSIDERED BY EXAMINER DATED MARCH 26, 2003, SHEET 1 of 1, UNDER "FOREIGN PATENT DOCUMENTS", ENTRY 2)

On the Face Page, in Field (56), under "FOREIGN PATENT DOCUMENTS", in Column 2, Line 4, delete "JP 1128548 8/2001" and insert - - EP 1128548 8/2001 - -, therefor.

(LIST OF REFERENCES CITED BY APPLICANT AND CONSIDERED BY EXAMINER DATED MARCH 26, 2003, SHEET 1 of 1, UNDER "FOREIGN PATENT DOCUMENTS", ENTRY 1)

In Column 3, Line 28, after "the" delete "a".  
(ORIGINALLY FILED SPECIFICATION DATED JULY 27, 2001, PAGE 7, LINE 2)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

December 7, 2007

/Sidney L. Weatherford, Reg #45602/

DATE

Sidney L. Weatherford  
Registration No. 45602

Attorney of Record

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,893,101 B2

APPLICATION NO. : 09/917,573

ISSUE DATE : May 17, 2005

INVENTOR(S) : Marra et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Face Page, in Field (56), under "FOREIGN PATENT DOCUMENTS", in Column 2, Line 3, delete "JP 1079515 2/2001" and insert - - EP 1079515 2/2001 - -, therefor.

On the Face Page, in Field (56), under "FOREIGN PATENT DOCUMENTS", in Column 2, Line 4, delete "JP 1128548 8/2001" and insert - - EP 1128548 8/2001 - -, therefor.

In Column 3, Line 28, after "the" delete "a".

MAILING ADDRESS OF SENDER (Please do not use customer number below):

6300 Legacy, MS EVR 1-C-11  
Plano, TX 75024  
972-583-8656

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Box 1450, Alexandria, VA 22313-1450.

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*